

S263249 - Damage Appraisal Fleet - GJ9053

General information

Fleet
SOCLIMA

Location
Care4Fleets LU2-Kehlen

Date & Time
05/03/2026 15:04

Inspection conditions
ok

Vehicle information

Brand
Renault

Color
Blanc

Lease
AYVENS - LEASECO

Model
Trafic

Mileage
84655

Edition
RENAULT TRAFIC 29 FOURGON MWB DSL - 2019
2.0 dCi 29 L2H1 Grand Confort

Fuel type
Diesel

Type
Van

Fuel level (%)
50

License Plate
GJ9053

Number of keys
2

VIN
VF1FL000364890768

Number of seats
3

Date first inscription
2020-11-17

Gearbox
manual

General remarks

-

Driver remarks

-

Advisor remarks

-

Adjustments

-

Summary Repair Costs (EUR VAT excl.)

Signatures

Rémy Voet

Driver



05/03/2026 15:04

Checklist

Yes No N/A

- | | | |
|---|--|--|
| <input checked="" type="radio"/> Certificate of conformity | <input checked="" type="radio"/> Triangle | <input checked="" type="radio"/> Radio |
| <input checked="" type="radio"/> Inscription document | <input checked="" type="radio"/> Safety jacket | <input type="radio"/> Dvd player |
| <input checked="" type="radio"/> Insurance document | <input checked="" type="radio"/> Fire extinguisher | <input type="radio"/> Cd dvd |
| <input checked="" type="radio"/> Valid insurance | <input type="radio"/> First aid kit | <input type="radio"/> Cd navigation |
| <input checked="" type="radio"/> Insurance valid until : 31/01/2027 | <input checked="" type="radio"/> Spare tyre | <input type="radio"/> Screen tv/dvd |
| <input checked="" type="radio"/> Maintenance book | <input type="radio"/> Runflat | <input type="radio"/> Apple carplay / Android auto |
| <input checked="" type="radio"/> Manual | <input type="radio"/> Tyre repair kit | <input type="radio"/> Gps navigation |
| <input checked="" type="radio"/> Technical control certificate | | <input type="radio"/> Towing hitch |
| <input checked="" type="radio"/> Valid until : 08/01/2027 | | <input checked="" type="radio"/> Antenna |
| <input type="radio"/> Fuel card | | <input type="radio"/> Open roof |
| <input type="radio"/> Alarm | | <input type="radio"/> Rear shelf/cover |

Diesel / Petrol / CNG

Fuel level
50

Vehicle status

Interior	Exterior	Smell	Service needed
Clean	Clean	OK	NO


Tyres

Tyre	Profile	Type	Brand	Size
Front left	5.0	Winter	Firestone	205/65R16
Front right	5.0	Winter	Firestone	205/65R16
Rear left	6.0	Summer	Bridgestone	205/65R16
Rear right	6.0	Summer	Bridgestone	205/65R16

Depreciation

Dépréciation (%)
53

Damage overview



Damage overview NOT ACCEPTABLE - New

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair
Interior	4	Seat front left	Left front seat	Hole	Smart	

Damage overview NOT ACCEPTABLE - Already present

Damage overview ACCEPTABLE

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair
Exterior	16	Light rear left	Left taillight	Cracked	Replace	
Exterior	17	Bumper rear	Rear bumper	Scratch	Replace	
Exterior	17	Bumper rear	Rear bumper	Scratch	Replace	
Exterior	15	Bonnet rear	Tailgate	Scratch + dent	Repair + Paint	
Exterior	21	Door rear right	Right rear door	Scratch + dent	Repair + Paint	
Exterior	24	Mirror right	Right mirror cover	Scratch	Smart	

Damage overview CLAIM

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair
Exterior	27	Roof	Roof	Dent	Repair + Paint	

General pictures



Damage overview NOT ACCEPTABLE - New pictures

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Interior	4	Seat front left	Left front seat	Hole	Smart		
 					<p>Comments</p> <p>Sous réserve de remplacement.</p>		

Damage overview NOT ACCEPTABLE - Already present pictures

Damage overview ACCEPTABLE - Pictures

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
-------------------	-------------	------	---------	-------------	--------	--------	------

Exterior	16	Light rear left	Left taillight	Cracked	Replace	
----------	----	-----------------	----------------	---------	---------	--




Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	17	Bumper rear	Rear bumper	Scratch	Replace		







Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	17	Bumper rear	Rear bumper	Scratch	Replace		







Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	15	Bonnet rear	Tailgate	Scratch + dent	Repair + Paint		




Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	21	Door rear right	Right rear door	Scratch + dent	Repair + Paint		



Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	24	Mirror right	Right mirror cover	Scratch	Smart		



Damage overview CLAIM - Pictures

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	27	Roof	Roof	Dent	Repair + Paint		



Comments

Claims 1

Link ONLINE version

[Click Here](#)