

## S267295 - Damage Appraisal Fleet - ZH6387

### General information

**Fleet**  
MERBAG

**Location**  
Care4Fleets LU2-Kehlen

**Driver**  
WILBOIS, Thomas

**Date & Time**  
31/03/2026 11:58

**Inspection conditions**  
ok

### Vehicle information

**Brand**  
Skoda  
**Model**  
Unknown Model

**Color**  
Blanc  
**Mileage**  
24720

**Lease**  
AYVENS - LEASECO

**Edition**  
SMART #3 BEV 66KWH PRO+ AUTO

**Fuel type**  
Electric

**Type**  
Car

**Battery level (%)**  
88

**License Plate**  
ZH6387

**Number of keys**  
1

**VIN**  
HESCR1C4XPS192412

**Number of seats**  
5

**Date first inscription**  
2024-06-14

**Gearbox**  
automatic

### General remarks

-

### Driver remarks

-

### Advisor remarks

-

### Adjustments

-

### Summary Repair Costs (EUR VAT excl.)


## Signatures

**Rémy Voet**



31/03/2026 11:58

**WILBOIS, Thomas**  
Driver



31/03/2026 11:58

## Checklist

Yes
  No
  N/A

- |  |  |   |
|--|--|---|
| <input checked="" type="radio"/> Certificate of conformity | <input checked="" type="radio"/> Triangle        | <input checked="" type="radio"/> Radio                        |
| <input checked="" type="radio"/> Inscription document      | <input checked="" type="radio"/> Safety jacket   | <input type="radio"/> Dvd player                              |
| <input type="radio"/> Insurance document                   | <input type="radio"/> Fire extinguisher          | <input type="radio"/> Cd dvd                                  |
| <input type="radio"/> Valid insurance                      | <input type="radio"/> First aid kit              | <input type="radio"/> Cd navigation                           |
| <input type="radio"/> Insurance valid until                | <input type="radio"/> Spare tyre                 | <input type="radio"/> Screen tv/dvd                           |
| <input checked="" type="radio"/> Maintenance book          | <input type="radio"/> Runflat                    | <input checked="" type="radio"/> Apple carplay / Android auto |
| <input checked="" type="radio"/> Manual                    | <input checked="" type="radio"/> Tyre repair kit | <input checked="" type="radio"/> Gps navigation               |
| <input type="radio"/> Technical control certificate        |  | <input type="radio"/> Towing hitch                            |
| <input checked="" type="radio"/> Valid until : 14/06/2028  |  | <input type="radio"/> Antenna                                 |
| <input type="radio"/> Fuel card                            |  | <input type="radio"/> Open roof                               |
| <input type="radio"/> Alarm                                |  | <input checked="" type="radio"/> Rear shelf/cover             |

## Electrical vehicle and plugin-hybride

Cable type	Amount
public	1

Varia	
Battery level	88%
Powerbox	No
Powerbox meter reading	0
Powerbox serial number	

## Vehicle status

Interior	Exterior	Smell	Service needed
Clean	Clean	OK	NO



## Tyres

Tyre	Profile	Type	Brand	Size
Front left	7.0	Winter	Goodyear	245/45R18
Front right	7.0	Winter	Goodyear	245/45R18
Rear left	6.0	Winter	Goodyear	245/45R18
Rear right	6.0	Winter	Goodyear	245/45R18

## Depreciation

**Dépréciation (%)**  
 25

## Damage overview



## Damage overview NOT ACCEPTABLE - New

## Damage overview NOT ACCEPTABLE - Already present

## Damage overview ACCEPTABLE

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair
Exterior	11	Door rear left	Left rear door	Scratch	Repair + Paint	
Exterior	12	Wing rear left	Left rear wing	Scratch	Polish	
Interior	15	Cover bonnet	Trunk cover	Scratch	Smart	

## Damage overview CLAIM


## General pictures





Damage overview NOT ACCEPTABLE - New pictures

Damage overview NOT ACCEPTABLE - Already present pictures

## Damage overview ACCEPTABLE - Pictures

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	11	Door rear left	Left rear door	Scratch	Repair + Paint		
							

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Exterior	12	Wing rear left	Left rear wing	Scratch	Polish		
							

Interior/exterior	Zone number	Zone	Subzone	Damage type	Advice	Repair	Cost
Interior	15	Cover bonnet	Trunk cover	Scratch	Smart		
							

## Link ONLINE version

[Click Here](#)